



## PERSONAL PROTECTIVE PRODUCTS

### USER INSTRUCTIONS

**For health and safety reasons, please read this information carefully**

This garment is classed as Personal Protective Equipment (PPE) by the EC Directive 89/686/EEC, and has been shown to comply with this directive through the European Standard EN ISO 20471:2013. The garment carries the CE mark to demonstrate compliance with the Directive.

These User Instructions apply to the coverall & coat ranges.

#### **1. Scope of Protection**

This protective clothing meets the requirements of:

Class 3 Area of visible background material

It is designed to provide conspicuity of the wearer in any light condition when viewed by operators of vehicles or other mechanized equipment during daylight conditions and under illumination of headlights in the dark.

#### **2. Limitations of Use**

The optical performance of this garment will ensure conspicuity against most backgrounds found in normal urban and rural situations. However, wearing a high visibility garment does not guarantee that the wearer will be visible under all conditions.

This garment does not protect against foul weather.

No item of protective clothing can provide full protection, and care must always be taken while carrying out the risk related activity

#### **3. Fitting and sizing**

Only wear garments of a suitable size. Garments which are too loose or too tight may restrict movement and may not provide the optimum level of protection. The wearer can only be protected if the garment is fully fastened.

#### **4. Modifications**

No garment should be modified in any way by the addition of extra pockets, fasteners, badges etc. In its' original state the garment complies with the European Standard and is CE marked accordingly. Any modification will invalidate the CE mark, and Alsico can accept no responsibility if this instruction is ignored.

#### **5. Aftercare**

Dirty clothing may lead to a reduction in the optical performance. To ensure optimum conspicuity the garment must be kept clean, and regular comparisons are recommended with a new garment. Do not use if heavily soiled. High visibility garments should be washed separately from other clothing. The wash temperature should not exceed 60°C. Do not use chlorine bleach. Do not overdry. Fabric temperature should not exceed 135°C during drying. High temperature tunnel drying may affect the performance of the reflective tape.

#### **6. Storage**

When not in use store the garment in a warm dry area away from direct sunlight.

#### **7. EC type examination by:**

**BTTG Testing & Certification Ltd**  
Unit 14, Wheel Forge Way, Trafford Park, Manchester. M17 1EH  
Notified Body No. 0338

**Alsico Laucuba Ltd**  
Pittman Way, Fulwood  
Preston. PR2 9ZD  
Tel. 01772 662500 Fax 01772 662510  
e-mail: [sales@alsico.co.uk](mailto:sales@alsico.co.uk) website: [www.alsico.co.uk](http://www.alsico.co.uk)

LBL00645